## Target Version

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| **Immediate (76)** | | | | | |
| 723 | 01 - Critical | imwww init script does not properly restart the server. | Hammel | 50 | 0.5.0 |
| 722 | 01 - Critical | imwww fails to recover from piboxd comm error | Hammel | 0 | 0.5.0 |
| 683 | 01 - Critical | AC power | Hammel | 20 | 0.5.0 |
| 1160 | 01 - Critical | Add support for multiple videos with the same name | Hammel | 0 | 3.0 - Corrino |
| 1159 | 01 - Critical | Add ability to upload a custom poster | Hammel | 0 | 3.0 - Corrino |
| 1158 | 01 - Critical | Server crashes when used in production. | Hammel | 0 | 3.0 - Corrino |
| 1153 | 01 - Critical | Migrate pisensors to use pigtk widgets. | Hammel | 0 | 3.0 - Corrino |
| 1102 | 01 - Critical | TouchProcessor fails on pinet to exit or notify on exit when running on pistore. | Hammel | 50 | 3.0 - Corrino |
| 1060 | 01 - Critical | Need store manager web UI | Hammel | 90 | 3.0 - Corrino |
| 883 | 01 - Critical | PiStore needs to respond to multicast queries | Hammel | 0 | 3.0 - Corrino |
| 700 | 01 - Critical | Need Phone App | Hammel | 50 | 3.0 - Corrino |
| 588 | 01 - Critical | File Manager for PiStore's | Hammel | 30 | 3.0 - Corrino |
| 134 | 01 - Critical | Need an init script to launch at power up | Hammel | 0 | Beta 1 |
| 1149 | 02 - High | Rewrite UI using pigtk-icontable and friends | Hammel | 0 | 3.0 - Corrino |
| 1117 | 02 - High | pidialer requires two presses of exit button to exit the app. | Hammel | 0 | 3.0 - Corrino |
| 1112 | 02 - High | Pidialer needs to center phone number on display widget. | Hammel | 0 | 3.0 - Corrino |
| 1110 | 02 - High | Xeon status bar needs to be larger so it's easier to see. | Hammel | 50 | 3.0 - Corrino |
| 1086 | 02 - High | Mount USB stores by partition labels, if available | Hammel | 0 | 3.0 - Corrino |
| 601 | 02 - High | File Management: web | Hammel | 10 | 3.0 - Corrino |
| 989 | 02 - High | rk818 is spewing to console | Hammel | 10 | Xeon 1.0 - Asimov |
| 667 | 03 - Medium | Set blink mode for operational mode | Hammel | 0 | 0.5.0 |
| 640 | 03 - Medium | imrest should provide a configuration API | Hammel | 0 | 0.5.0 |
| 1155 | 03 - Medium | Check pistore and raspi2fbd package ownerships | Hammel | 0 | 3.0 - Corrino |
| 1150 | 03 - Medium | Add "jump to" API for pigtk-icontable | Hammel | 0 | 3.0 - Corrino |
| 1138 | 03 - Medium | pinet autoconf on debian 12 doesn't support --enable-xeon option. | Hammel | 0 | 3.0 - Corrino |
| 1137 | 03 - Medium | No wifi interface found | Hammel | 20 | 3.0 - Corrino |
| 1134 | 03 - Medium | Replace Hidden SSID button with show/hide mac button. | Hammel | 50 | 3.0 - Corrino |
| 1126 | 03 - Medium | Migrate clock and wifiscan widgets to pigtk | Hammel | 0 | 3.0 - Corrino |
| 1101 | 03 - Medium | Update Jarvis registration to match new imrest requirements. | Hammel | 10 | 3.0 - Corrino |
| 1100 | 03 - Medium | Update lightsw registration to match new imrest requirements. | Hammel | 0 | 3.0 - Corrino |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 1098 | 03 - Medium | PiPlayer locks up if left alone for awhile. | Hammel | 0 | 3.0 - Corrino |
| 1080 | 03 - Medium | Sensors: 1 port power switch | Hammel | 0 | 3.0 - Corrino |
| 1063 | 03 - Medium | Add phone mode to PiNet to configure WiFi | Hammel | 90 | 3.0 - Corrino |
| 889 | 03 - Medium | Migrate to new db format for TV | Hammel | 10 | 3.0 - Corrino |
| 522 | 03 - Medium | Switch UI to something like Plex | Hammel | 10 | 3.0 - Corrino |
| 156 | 03 - Medium | post installation should disable X.org in PiBox | Hammel | 70 | Beta 1 |
| 931 | 03 - Medium | Add project top level grouping | Hammel | 0 | Writers Workship |
| 929 | 03 - Medium | .deb build failing on Debian 11 | Hammel | 0 | Writers Workship |
| 979 | 03 - Medium | Add psplash to Xeon metabuild | Hammel | 0 | Xeon 1.0 - Asimov |
| 877 | 03 - Medium | Update build.help | Hammel | 0 | Xeon 1.0 - Asimov |
| 668 | 04 - Low | Verify blink modes | Hammel | 0 | 0.5.0 |
| 647 | 04 - Low | Code review imlightsw to look for leaks | Hammel | 0 | 0.5.0 |
| 589 | 04 - Low | Monitor Setup | Hammel | 30 | 0.5.0 |
| 1152 | 04 - Low | piboxd needs a test mode | Hammel | 0 | 3.0 - Corrino |
| 1111 | 04 - Low | pidialer needs to scale button to fill drawing area | Hammel | 0 | 3.0 - Corrino |
| 1076 | 04 - Low | Enable opengl-demos in buildroot config for testing graphics | Hammel | 30 | 3.0 - Corrino |
| 775 | 04 - Low | Check if migration to Buildroot recommended customizations is warranted | Hammel | 30 | 3.0 - Corrino |
| 254 | 04 - Low | Investigate use of Wifi Direct | Hammel | 0 | 3.0 - Corrino |
| 697 | 04 - Low | All apps that support it need updating to new touchscreen APIs | Hammel | 0 | Xeon 1.0 - Asimov |
| 710 | 05 - Very Low | Investigate camera module | Hammel | 0 | 0.5.0 |
| 676 | 05 - Very Low | Verify breadboard designs in Fritzing are up to date | Hammel | 20 | 0.5.0 |
| 650 | 05 - Very Low | Add lsb_release as a third party package | Hammel | 0 | 0.5.0 |
| 1097 | 05 - Very Low | Remove "under voltage" warning from dmesg | Hammel | 0 | 3.0 - Corrino |
| 1088 | 05 - Very Low | Investigate potential sensors for Ironman. | Hammel | 0 | 3.0 - Corrino |
| 1087 | 05 - Very Low | Build hardware prototype | Hammel | 0 | 3.0 - Corrino |
| 1083 | 05 - Very Low | PiSensor:  add PiStore summary pages | Hammel | 0 | 3.0 - Corrino |
| 1082 | 05 - Very Low | PiSensor:  Add remote webcam interface | Hammel | 0 | 3.0 - Corrino |
| 1079 | 05 - Very Low | Port PiClock to Xeon | Hammel | 0 | 3.0 - Corrino |
| 1077 | 05 - Very Low | Add pair button to UI | Hammel | 0 | 3.0 - Corrino |
| 1058 | 05 - Very Low | Add genre search to top bar | Hammel | 0 | 3.0 - Corrino |
| 1044 | 05 - Very Low | System Integration Tests for Corrino (v3.0) Release | Hammel | 0 | 3.0 - Corrino |
| 1021 | 05 - Very Low | Add support for vgencmd options | Hammel | 0 | 3.0 - Corrino |
| 998 | 05 - Very Low | Make toolchain package | Hammel | 0 | 3.0 - Corrino |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 988 | 05 - Very Low | Add Battery status to launcher for xeon. | Hammel | 10 | 3.0 - Corrino |
| 964 | 05 - Very Low | Should pistore/pisentry be rotated 180 degrees? | Hammel | 0 | 3.0 - Corrino |
| 897 | 05 - Very Low | Add option for using a local source archive | Hammel | 0 | 3.0 - Corrino |
| 831 | 05 - Very Low | Show MAC address in imwww | Hammel | 0 | 3.0 - Corrino |
| 794 | 05 - Very Low | Add URL streaming option for AutoKiosk system | Hammel | 10 | 3.0 - Corrino |
| 791 | 05 - Very Low | Interesting Hardware and Software Ideas | Hammel | 0 | 3.0 - Corrino |
| 701 | 05 - Very Low | Need Text App | Hammel | 10 | 3.0 - Corrino |
| 472 | 05 - Very Low | Boot time speedups | Hammel | 70 | 3.0 - Corrino |
| 122 | Critical | Create opkg for toolchain debug tools | Hammel | 50 | 0.08.0 - DSP/SGX |
| 132 | Critical | Integrate xbmc patches from PiBox into buildroot | Hammel | 0 | 0.11.0 - Preview Release |
| 131 | Critical | Integrate opkg patches from PiBox for buildroot | Hammel | 0 | 0.11.0 - Preview Release |
| 124 | High | Rev SGX to 4.08.00.01 | Hammel | 0 | 0.08.0 - DSP/SGX |
| 95 | Medium | Verify DSP/gstreamer tools allow video playback | Hammel | 70 | 0.08.0 - DSP/SGX |
| **Urgent (62)** | | | | | |
| 636 | 01 - Critical | If wlan0 does not support more than one channel then client and AP must use same channel | Hammel | 0 | 0.9.0 |
| 1096 | 01 - Critical | Need a log rotator | Hammel | 0 | 3.0 - Corrino |
| 1000 | 01 - Critical | Validate VideoFE against a large database. | Hammel | 10 | 3.0 - Corrino |
| 971 | 01 - Critical | PiCam starts to lag, then crashes. | Hammel | 0 | 3.0 - Corrino |
| 965 | 01 - Critical | Review alternatives to RaspberryPi due to supply chain issues | Hammel | 0 | 3.0 - Corrino |
| 941 | 01 - Critical | Long pause after restart and animation stops | Hammel | 0 | 3.0 - Corrino |
| 936 | 01 - Critical | Switching webcam resolutions is flakey. | Hammel | 0 | 3.0 - Corrino |
| 935 | 01 - Critical | dhcpd.conf does not contain the correct interface IP network. | Hammel | 0 | 3.0 - Corrino |
| 926 | 01 - Critical | Scanner not working if dongle connected after boot. | Hammel | 0 | 3.0 - Corrino |
| 920 | 01 - Critical | Typing any key other than forward/back arrows locks up the app | Hammel | 0 | 3.0 - Corrino |
| 919 | 01 - Critical | Can't get web interface on media system | Hammel | 0 | 3.0 - Corrino |
| 887 | 01 - Critical | Update all cross.sh for new HW/BIT of dev platform | Hammel | 0 | 3.0 - Corrino |
| 878 | 01 - Critical | Add ustreamer to support rtsp/h.264 to mjpeg streaming | Hammel | 0 | 3.0 - Corrino |
| 804 | 01 - Critical | networkRestart should fork/exec instead of system(cmd) | Hammel | 0 | 3.0 - Corrino |
| 802 | 01 - Critical | Add support for GM_COMMIT | Hammel | 0 | 3.0 - Corrino |
| 745 | 01 - Critical | Add webcam recordings | Hammel | 10 | 3.0 - Corrino |
| 744 | 01 - Critical | add webcam motion detection | Hammel | 0 | 3.0 - Corrino |
| 730 | 01 - Critical | Add upgrade tools | Hammel | 0 | 3.0 - Corrino |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 715 | 01 - Critical | Why is image (re: picture) display so slow? | Hammel | 60 | 3.0 - Corrino |
| 175 | 01 - Critical | Addon: network configuration | Hammel | 0 | Beta 1 |
| 675 | 02 - High | Code cleanup in imrest | Hammel | 0 | 0.9.0 |
| 1139 | 02 - High | Make sure KMS is being used and fbtft is deprecated | Hammel | 0 | 3.0 - Corrino |
| 1078 | 02 - High | Moisture Sensor | Hammel | 0 | 3.0 - Corrino |
| 1073 | 02 - High | Make rk818-bat stop spewing to serial console | Hammel | 70 | 3.0 - Corrino |
| 993 | 02 - High | PiSentry: sometimes takes awhile to exit.  And may not restart without power cycle. | Hammel | 0 | 3.0 - Corrino |
| 970 | 02 - High | Enable ccache use in all builds. | Hammel | 0 | 3.0 - Corrino |
| 958 | 02 - High | Update pmwiki documentation | Hammel | 50 | 3.0 - Corrino |
| 944 | 02 - High | On RPi 1, change animation to 90 degree rotations | Hammel | 0 | 3.0 - Corrino |
| 937 | 02 - High | Crash after channel selection | Hammel | 0 | 3.0 - Corrino |
| 925 | 02 - High | IP address does not get updated when switching between interfaces | Hammel | 0 | 3.0 - Corrino |
| 923 | 02 - High | Setting new time does not stick | Hammel | 0 | 3.0 - Corrino |
| 922 | 02 - High | When in artist mode and browsing, ESC could take you back to artist mode. | Hammel | 0 | 3.0 - Corrino |
| 921 | 02 - High | Playback doesn't support FF and Rewind features of omxplayer | Hammel | 0 | 3.0 - Corrino |
| 899 | 02 - High | Add docker builds for rpm and deb distros | Hammel | 0 | 3.0 - Corrino |
| 892 | 02 - High | Details->Real Title is not cleared with new entry display | Hammel | 0 | 3.0 - Corrino |
| 890 | 02 - High | Multipart titles don't get found | Hammel | 0 | 3.0 - Corrino |
| 798 | 02 - High | Sensor: 4 port power switch | Hammel | 0 | 3.0 - Corrino |
| 759 | 02 - High | Add packaging to metabuild | Hammel | 0 | 3.0 - Corrino |
| 731 | 02 - High | Automate upgrades | Hammel | 10 | 3.0 - Corrino |
| 611 | 02 - High | tslib very out of date | Hammel | 0 | 3.0 - Corrino |
| 159 | 02 - High | keyboard/mouse input doesn't work when xbmc starts | Hammel | 0 | Beta 1 |
| 135 | 02 - High | Need to integrate add-ons build to xbmcbox | Hammel | 0 | Beta 1 |
| 608 | 03 - Medium | Add daemon mode to imgpio | Hammel | 0 | 0.9.0 |
| 586 | 03 - Medium | PiSensor App config/browse | Hammel | 20 | 0.9.0 |
| 302 | 03 - Medium | JSONParser reports errors to console | Hammel | 0 | 0.9.0 |
| 1133 | 03 - Medium | pinet configure scripts enable-xeon doesn't work on Debian 12. | Hammel | 0 | 3.0 - Corrino |
| 1054 | 03 - Medium | Grab genre list next to video json | Hammel | 10 | 3.0 - Corrino |
| 1053 | 03 - Medium | Add support for retrieving and selecting alternative posters | Hammel | 0 | 3.0 - Corrino |
| 1052 | 03 - Medium | Add support for scanning an individual selection | Hammel | 0 | 3.0 - Corrino |
| 1051 | 03 - Medium | Add support for multi-part videos | Hammel | 0 | 3.0 - Corrino |
| 1011 | 03 - Medium | Remove or disable keyboard handling bits from pmsui | Hammel | 0 | 3.0 - Corrino |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 990 | 03 - Medium | Streaming RTSP cameras as webcams | Hammel | 0 | 3.0 - Corrino |
| 972 | 03 - Medium | Plans for 3.0 - Corrino release. | Hammel | 10 | 3.0 - Corrino |
| 933 | 03 - Medium | Disabling an interface and saving/applying does not update the IP field | Hammel | 0 | 3.0 - Corrino |
| 828 | 03 - Medium | All daemons need shutdown in prerm | Hammel | 0 | 3.0 - Corrino |
| 930 | 03 - Medium | Show only notes in a given category | Hammel | 0 | Writers Workship |
| 440 | 04 - Low | wifi/hostapd generates lots of log messages | Hammel | 20 | 3.0 - Corrino |
| 643 | 05 - Very Low | Build backup imlightsw circuits | Hammel | 0 | 0.9.0 |
| 830 | 05 - Very Low | pinet crashes at button press | Hammel | 10 | 3.0 - Corrino |
| 289 | 05 - Very Low | Port RTL8188CUS driver to PiBox | Hammel | 70 | 3.0 - Corrino |
| 125 | Critical | Integrate new xorg driver | Hammel | 0 | 0.08.0 - DSP/SGX |
| 116 | High | Add Meego UI for connman as a Buildroot package | Hammel | 0 | 0.08.0 - DSP/SGX |
| **High (28)** | | | | | |
| 68 | | Need to change binary prefixes from mb to bui to differentiate from matchbox code | Hammel | 0 | |
| 504 | 01 - Critical | IoT security | Hammel | 50 | 1.0.0 - Hari Seldon |
| 891 | 01 - Critical | Bad titles should be editable and re-scanned. | Hammel | 0 | 3.0 - Corrino |
| 932 | 01 - Critical | Allow passing command line arguments via shell script. | Hammel | 0 | Writers Workship |
| 781 | 02 - High | Add UI for system configuration | Hammel | 0 | 3.0 - Corrino |
| 776 | 02 - High | Add theme selection capability with preview | Hammel | 0 | 3.0 - Corrino |
| 555 | 02 - High | Lockup when USB stick runs out of space | Hammel | 0 | 3.0 - Corrino |
| 487 | 02 - High | Do something with msgQueue/Processor functions in libpibox | Hammel | 0 | 3.0 - Corrino |
| 441 | 02 - High | Add display rotatation/flip | Hammel | 0 | 3.0 - Corrino |
| 593 | 03 - Medium | door/window sensor | Hammel | 0 | 1.0.0 - Hari Seldon |
| 578 | 03 - Medium | Monitor Enclosure | Hammel | 0 | 1.0.0 - Hari Seldon |
| 1049 | 03 - Medium | Write network events to FIFO file. | Hammel | 10 | 3.0 - Corrino |
| 992 | 03 - Medium | PiNet sets wireless power off. | Hammel | 0 | 3.0 - Corrino |
| 966 | 03 - Medium | Consider migrating to full AV bridging for webcam support | Hammel | 0 | 3.0 - Corrino |
| 953 | 03 - Medium | Migrate to SPDX license header in all source code, including apps | Hammel | 0 | 3.0 - Corrino |
| 903 | 03 - Medium | New "Large Term" should be same as initial large term | Hammel | 0 | 3.0 - Corrino |
| 902 | 03 - Medium | Default of TKIP with WPA2 should be changed to CCMP | Hammel | 0 | 3.0 - Corrino |
| 901 | 03 - Medium | GUI writes empty nameserver entries | Hammel | 0 | 3.0 - Corrino |
| 900 | 03 - Medium | Non-keypad arrows keys crash the GUI | Hammel | 0 | 3.0 - Corrino |
| 868 | 03 - Medium | webui webcam has white bar across the bottom. | Hammel | 0 | 3.0 - Corrino |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 862 | 03 - Medium | piboxMsg() wants response length followed by response but not all messages provide it | Hammel | 0 | 3.0 - Corrino |
| 750 | 03 - Medium | Extend pmsg tests | Hammel | 0 | 3.0 - Corrino |
| 631 | 03 - Medium | Init scripts should use $() syntax instead of back-ticks for grabbing output from a command. | Hammel | 0 | 3.0 - Corrino |
| 160 | 03 - Medium | The Raspbmc addon is broken when applied to PiBox | Hammel | 10 | Beta 2 |
| 994 | 05 - Very Low | In PiSentry, there are two icons but aligned for three | Hammel | 10 | 3.0 - Corrino |
| 110 | Critical | verify build on Ubuntu | Hammel | 0 | 0.07.0 - Networking |
| 101 | Critical | add omapfbplay to rootfs build | Hammel | 20 | 0.08.0 - DSP/SGX |
| 9 | Medium | Surf package for buildroot | Hammel | 60 | 0.10.0 - BUI Features |
| **Normal (69)** | | | | | |
| 96 | | enable audio support | Hammel | 0 | 0.11.0 - Preview Release |
| 32 | | Support Xrm for simplified configuration capabilities. | Hammel | 0 | 1.0 |
| 62 | | Write up on the wiki how to modify the boot script, build it and use it | Hammel | 0 | 1.0 - Galileo |
| 11 | | Track availability of Flash on ARM | Hammel | 20 | 1.0 - Galileo |
| 10 | | Review open source flash players | Hammel | 10 | 1.0 - Galileo |
| 633 | 02 - High | Crashes on Ironman distro | Hammel | 0 | 2.0 - Harkonnen |
| 1033 | 02 - High | Preload icons | Hammel | 20 | 3.0 - Corrino |
| 806 | 02 - High | Update wiki message API documentation | Hammel | 0 | 3.0 - Corrino |
| 490 | 03 - Medium | ESP8266 sleep while maintaining wifi | Hammel | 10 | 1.0.0 - Hari Seldon |
| 1116 | 03 - Medium | Add support for styles to pigtk | Hammel | 10 | 3.0 - Corrino |
| 1032 | 03 - Medium | Speed up animation | Hammel | 10 | 3.0 - Corrino |
| 995 | 03 - Medium | Add option to clone using https instead of git | Hammel | 0 | 3.0 - Corrino |
| 984 | 03 - Medium | Make a list of required apps for 3.0 release | Hammel | 90 | 3.0 - Corrino |
| 854 | 03 - Medium | Consider ReadTheDocs for documentation | Hammel | 0 | 3.0 - Corrino |
| 792 | 03 - Medium | Try adding opengl to cairo in Launcher | Hammel | 70 | 3.0 - Corrino |
| 774 | 03 - Medium | Verify Buildroot uses BR2_PER_PACKAGE_DIRECTORIES | Hammel | 0 | 3.0 - Corrino |
| 756 | 03 - Medium | PiRadio | Hammel | 0 | 3.0 - Corrino |
| 752 | 03 - Medium | Videolib sometimes doesn't exit with File->Quit | Hammel | 0 | 3.0 - Corrino |
| 732 | 03 - Medium | PiBox with Docker | Hammel | 40 | 3.0 - Corrino |
| 728 | 03 - Medium | Review possible DRM with X.org | Hammel | 20 | 3.0 - Corrino |
| 565 | 03 - Medium | Multiple IP Address fields | Hammel | 0 | 3.0 - Corrino |
| 526 | 03 - Medium | Consider migrating to using Plex database | Hammel | 10 | 3.0 - Corrino |
| 516 | 03 - Medium | Finish port of msgQueue/queueProessor | Hammel | 0 | 3.0 - Corrino |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 483 | 03 - Medium | Need pncShutdown to reverse pncInit and clear all lists | Hammel | 0 | 3.0 - Corrino |
| 460 | 03 - Medium | Review BananaPi as replacement for RaspberryPi | Hammel | 30 | 3.0 - Corrino |
| 384 | 03 - Medium | Add support for interfacing with display via Android | Hammel | 50 | 3.0 - Corrino |
| 368 | 03 - Medium | Add support for WiiMote | Hammel | 0 | 3.0 - Corrino |
| 367 | 03 - Medium | May need a way to stabilize webcam | Hammel | 0 | 3.0 - Corrino |
| 365 | 03 - Medium | Customizations should go on vfat partition, not under /etc | Hammel | 0 | 3.0 - Corrino |
| 319 | 03 - Medium | -t option is not working on the desktop | Hammel | 0 | 3.0 - Corrino |
| 212 | 03 - Medium | Review integration of SPI and I2C support | Hammel | 0 | 3.0 - Corrino |
| 482 | 03 - Medium | Add remote connection option | Hammel | 0 | 4.1 |
| 481 | 03 - Medium | Consider adding support for Markup language | Hammel | 0 | 4.1 |
| 480 | 03 - Medium | Add ability to link various notes together | Hammel | 0 | 4.1 |
| 479 | 03 - Medium | Add porter-stemmer to search functions | Hammel | 0 | 4.1 |
| 478 | 03 - Medium | encrypt notes | Hammel | 0 | 4.1 |
| 477 | 03 - Medium | Flesh out build.help for current version. | Hammel | 0 | 4.1 |
| 476 | 03 - Medium | Add configurable autosave period to boot.propertie | Hammel | 0 | 4.1 |
| 475 | 03 - Medium | Upgrade SWT | Hammel | 0 | 4.1 |
| 474 | 03 - Medium | Integrate CDShelf | Hammel | 0 | 4.1 |
| 983 | 03 - Medium | Investigate towboot installed to eMMC | Hammel | 0 | Xeon 1.0 - Asimov |
| 982 | 03 - Medium | Rebuild tow-boot to default to PiBox Dev Platform | Hammel | 0 | Xeon 1.0 - Asimov |
| 711 | 03 - Medium | Reduce power consumption when not in use | Hammel | 0 | Xeon 1.0 - Asimov |
| 708 | 03 - Medium | Need network config app | Hammel | 20 | Xeon 1.0 - Asimov |
| 702 | 03 - Medium | Need Contacts App | Hammel | 0 | Xeon 1.0 - Asimov |
| 848 | 04 - Low | lcdshow pkg install - can't read etc/modules | Hammel | 60 | 3.0 - Corrino |
| 371 | 04 - Low | Media Server and Media Player case models | Hammel | 30 | 3.0 - Corrino |
| 149 | 04 - Low | Create Beta 1 release | Hammel | 0 | Beta 1 |
| 150 | 05 - Very Low | Announce Beta1 to News | Hammel | 0 | Beta 1 |
| 24 | Critical | Remove XML and themes from window manager | Hammel | 70 | |
| 63 | High | Make a patch against u-boot BeagleBoard config to reduce boot delay to build-configurable time. | Hammel | 0 | 0.08.0 - DSP/SGX |
| 35 | High | Make panels that slide in from the sides. | Hammel | 0 | 1.0 |
| 7 | High | Need a scrolling menu applet for the panel | Hammel | 20 | 1.0 |
| 34 | Low | Does the window manager need XComposite support? | Hammel | 0 | 1.0 |
| 33 | Low | X cursor should auto-hide after (N) periods of inactivity. | Hammel | 0 | 1.0 |
| 31 | Low | Allow no more than (N) non-panel clients. | Hammel | 0 | 1.0 |

| # | Severity | Subject | Assignee | % Done | Target version |
|---|---|---|---|---|---|
| 30 | Low | Make panel clients raise above all other clients. | Hammel | 0 | 1.0 |
| 29 | Low | Make panel clients raise above all other clients. | Hammel | 0 | 1.0 |
| 28 | Low | Make all X clients except panels full screen. | Hammel | 0 | 1.0 |
| 86 | Low | Create an XBMC build - make it an opkg | Hammel | 0 | 1.0 - Galileo |
| 60 | Low | Fix the S-Video output overscan problem. | Hammel | 0 | 1.0 - Galileo |
| 53 | Low | dd of rootfs image doesn't use up full 2nd partition on SD card | Hammel | 0 | 1.0 - Galileo |
| 83 | Medium | Panel crashes when I click on it on BeagleBoard | Hammel | 50 | 1.0 |
| 41 | Medium | Configuration information should be cached before writing to SD card | Hammel | 0 | 1.0 |
| 14 | Medium | Tool for creating URL snapshots | Hammel | 0 | 1.0 |
| 5 | Medium | UI Configuration Tool | Hammel | 0 | 1.0 |
| 64 | Medium | Boot time improvements | Hammel | 0 | 1.0 - Galileo |
| 42 | Medium | Update env vars in u-boot code | Hammel | 10 | 1.0 - Galileo |
| 16 | Medium | Add a boot splash and turn off console output | Hammel | 10 | 1.0 - Galileo |
| **Low (14)** | | | | | |
| 600 | 03 - Medium | Admin configuration: web | Hammel | 0 | 2.0.0 - Dors Venabili |
| 599 | 03 - Medium | View sensor status: web | Hammel | 0 | 2.0.0 - Dors Venabili |
| 598 | 03 - Medium | Admin configuration: mobile | Hammel | 0 | 2.0.0 - Dors Venabili |
| 597 | 03 - Medium | View sensor status: mobile | Hammel | 0 | 2.0.0 - Dors Venabili |
| 592 | 03 - Medium | Sensor Enclosure | Hammel | 0 | 2.0.0 - Dors Venabili |
| 591 | 03 - Medium | battery power | Hammel | 0 | 2.0.0 - Dors Venabili |
| 587 | 03 - Medium | Contacts UI | Hammel | 0 | 2.0.0 - Dors Venabili |
| 584 | 03 - Medium | Battery backup | Hammel | 0 | 2.0.0 - Dors Venabili |
| 575 | 03 - Medium | Backup Battery Circuit board | Hammel | 0 | 2.0.0 - Dors Venabili |
| 574 | 03 - Medium | 2G/3G support based on Raspberry Pi phone build | Hammel | 0 | 2.0.0 - Dors Venabili |
| 324 | 03 - Medium | usbhandler.sh needs to support multiple modules per device | Hammel | 10 | 3.0 - Corrino |
| 210 | 04 - Low | Research fail2ban | Hammel | 0 | 3.0 - Corrino |
| 500 | 05 - Very Low | Implement stepper motor control | Hammel | 0 | 2.0.0 - Dors Venabili |
| 173 | 05 - Very Low | Timestamp variable TM is not updated on the fly | Hammel | 0 | 3.0 - Corrino |