

by Priority and Severity

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
Immediate (72)								
722	01 - Critical	New	imwww fails to recover from piboxd comm error	Bug	Hammel	20 Oct 2019 12:00	0	0.5.0
134	01 - Critical	New	Need an init script to launch at power up	Feature	Hammel	10 Feb 2013 14:41	0	Beta 1
1138	03 - Medium	New	pinet autoconf on debian 12 doesn't support --enable-xeon option.	Bug	Hammel	25 Apr 2024 15:13	0	3.0 - Corrino
1132	03 - Medium	New	Horizontally center text in list items of a pigtk-simplelist.	Feature	Hammel	22 Apr 2024 22:57	0	3.0 - Corrino
1126	03 - Medium	New	Migrate clock and wifiscan widgets to pigtk	Feature	Hammel	16 Apr 2024 21:16	0	3.0 - Corrino
1117	03 - Medium	New	pidialer requires two presses of exit button to exit the app.	Bug	Hammel	09 Apr 2024 10:48	0	3.0 - Corrino
1112	03 - Medium	New	Pidialer needs to center phone number on display widget.	Bug	Hammel	21 Mar 2024 11:50	0	3.0 - Corrino
1110	03 - Medium	New	Xeon status bar needs to be larger so it's easier to see.	Bug	Hammel	21 Mar 2024 09:34	0	3.0 - Corrino
1102	03 - Medium	New	TouchProcessor fails to exit or notify on exit on pistore.	Bug	Hammel	04 Mar 2024 16:17	0	3.0 - Corrino
1100	03 - Medium	New	Update lightsw registration to match new imrest requirements.	Feature	Hammel	17 Feb 2024 17:00	0	3.0 - Corrino
1098	03 - Medium	New	PiPlayer locks up if left alone for awhile.	Bug	Hammel	15 Jan 2024 15:30	0	3.0 - Corrino
1086	03 - Medium	New	Mount USB stores by partition labels, if available	Feature	Hammel	23 Nov 2023 19:51	0	3.0 - Corrino
1080	03 - Medium	New	Sensors: 1 port power switch	Feature	Hammel	25 Apr 2024 14:47	0	3.0 - Corrino
1060	03 - Medium	New	Need store manager web UI	Feature	Hammel	30 Oct 2023 20:32	0	3.0 - Corrino
979	03 - Medium	New	Add psplash to Xeon metabuild	Feature	Hammel	18 May 2023 16:27	0	Xeon 1.0 - Asimov
931	03 - Medium	New	Add project top level grouping	Feature	Hammel	13 Jan 2023 14:33	0	Writers Workshop
929	03 - Medium	New	.deb build failing on Debian 11	Bug	Hammel	13 Jan 2023 14:31	0	Writers Workshop
877	03 - Medium	New	Update build.help	Action Item	Hammel	18 May 2023 11:56	0	Xeon 1.0 - Asimov
667	03 - Medium	New	Set blink mode for operational mode	Feature	Hammel	09 Sep 2018 15:22	0	0.5.0
640	03 - Medium	New	imrest should provide a configuration API	Feature	Hammel	12 Jul 2018 13:13	0	0.5.0
1136	04 - Low	New	Cleanup pigtk widget debug messages	Bug	Hammel	25 Apr 2024 13:59	0	3.0 - Corrino
1111	04 - Low	New	pidialer needs to scale button to fill drawing area	Bug	Hammel	21 Mar 2024 11:25	0	3.0 - Corrino
883	04 - Low	New	PiStore needs to respond to multicast queries	Feature	Hammel	30 Oct 2023 20:35	0	3.0 - Corrino
697	04 - Low	New	All apps that support it need updating to new touchscreen APIs	Bug	Hammel	18 May 2023 12:02	0	Xeon 1.0 - Asimov
668	04 - Low	New	Verify blink modes	Action Item	Hammel	09 Sep 2018 15:22	0	0.5.0
647	04 - Low	New	Code review imlightsw to look for leaks	Testing	Hammel	23 Mar 2020 10:33	0	0.5.0
588	04 - Low	New	File Manager for PiStore's	Feature	Hammel	28 Apr 2024 20:19	0	3.0 - Corrino
1097	05 - Very Low	New	Remove "under voltage" warning from dmesg	Bug	Hammel	12 Jan 2024 16:37	0	3.0 - Corrino
1088	05 - Very Low	New	Investigate potential sensors for Ironman.	Feature	Hammel	23 Nov 2023 23:20	0	3.0 - Corrino
1087	05 - Very Low	New	Build hardware prototype	Feature	Hammel	23 Apr 2024 13:37	0	3.0 - Corrino

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
1083	05 - Very Low	New	PiSensor: add PiStore summary pages	Feature	Hammel	16 Nov 2023 14:43	0	3.0 - Corrino
1082	05 - Very Low	New	PiSensor: Add remote webcam interface	Feature	Hammel	16 Nov 2023 14:39	0	3.0 - Corrino
1079	05 - Very Low	New	Port PiClock to Xeon	Feature	Hammel	16 Nov 2023 11:28	0	3.0 - Corrino
1077	05 - Very Low	New	Add pair button to UI	Feature	Hammel	15 Nov 2023 15:55	0	3.0 - Corrino
1058	05 - Very Low	New	Add genre search to top bar	Feature	Hammel	24 Oct 2023 15:57	0	3.0 - Corrino
1044	05 - Very Low	New	System Integration Tests for Corrino (v3.0) Release	Testing	Hammel	15 Nov 2023 22:15	0	3.0 - Corrino
1021	05 - Very Low	New	Add support for vgenclmd options	Feature	Hammel	04 Aug 2023 17:25	0	3.0 - Corrino
998	05 - Very Low	New	Make toolchain package	Feature	Hammel	02 Aug 2023 17:36	0	3.0 - Corrino
964	05 - Very Low	New	Should pistore/pisentry be rotated 180 degrees?	Feature	Hammel	02 Jun 2023 15:25	0	3.0 - Corrino
897	05 - Very Low	New	Add option for using a local source archive	Feature	Hammel	16 Sep 2022 22:42	0	3.0 - Corrino
831	05 - Very Low	New	Show MAC address in imwww	Bug	Hammel	30 Oct 2023 20:37	0	3.0 - Corrino
791	05 - Very Low	New	Interesting Hardware and Software Ideas	Alternative Idea	Hammel	30 Apr 2024 13:24	0	3.0 - Corrino
710	05 - Very Low	New	Investigate camera module	Action Item	Hammel	23 Mar 2020 10:30	0	0.5.0
701	05 - Very Low	New	Need Text App	Feature	Hammel	16 Nov 2023 14:19	10	3.0 - Corrino
650	05 - Very Low	New	Add lsb_release as a third party package	Feature	Hammel	28 Jul 2018 10:57	0	0.5.0
132	Critical	New	Integrate xbmc patches from PiBox into buildroot	Action Item	Hammel	21 Nov 2012 13:43	0	0.11.0 - Preview Release
131	Critical	New	Integrate opkg patches from PiBox for buildroot	Action Item	Hammel	21 Nov 2012 13:41	0	0.11.0 - Preview Release
124	High	New	Rev SGX to 4.08.00.01	Action Item	Hammel	28 Oct 2012 17:03	0	0.08.0 - DSP/SGX
1140	01 - Critical	In Progress	Missing tools for production system	Bug	Hammel	02 May 2024 15:34	10	3.0 - Corrino
1137	01 - Critical	In Progress	No wifi interface found	Bug	Hammel	28 Apr 2024 15:08	20	3.0 - Corrino
1134	01 - Critical	In Progress	Replace Hidden SSID button with show/hide mac button.	Feature	Hammel	26 Apr 2024 16:28	50	3.0 - Corrino
723	01 - Critical	In Progress	imwww init script does not properly restart the server.	Bug	Hammel	27 Oct 2019 23:04	50	0.5.0
683	01 - Critical	In Progress	AC power	Feature	Hammel	08 Feb 2019 10:47	20	0.5.0
1063	02 - High	In Progress	Add phone mode to PiNet to configure WiFi	Feature	Hammel	24 Apr 2024 20:05	90	3.0 - Corrino
989	02 - High	In Progress	rk818 is spewing to console	Bug	Hammel	19 May 2023 14:26	10	Xeon 1.0 - Asimov
1130	03 - Medium	In Progress	Migrate launcher UI to a pigtk widget.	Feature	Hammel	28 Apr 2024 23:29	20	3.0 - Corrino
1101	03 - Medium	In Progress	Update Jarvis registration to match new imrest requirements.	Bug	Hammel	26 Apr 2024 16:32	10	3.0 - Corrino
889	03 - Medium	In Progress	Migrate to new db format for TV	Feature	Hammel	20 Oct 2023 21:40	10	3.0 - Corrino
700	03 - Medium	In Progress	Need Phone App	Feature	Hammel	23 Apr 2024 16:30	50	3.0 - Corrino
601	03 - Medium	In Progress	File Management: web	Feature	Hammel	28 Apr 2024 15:35	10	3.0 - Corrino
522	03 - Medium	In Progress	Switch UI to something like Plex	Feature	Hammel	23 Oct 2023 20:45	10	3.0 - Corrino
156	03 - Medium	In Progress	post installation should disable X.org in PiBox	Action Item	Hammel	15 Feb 2013 07:58	70	Beta 1

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
1076	04 - Low	In Progress	Enable opengl-demos in buildroot config for testing graphics	Feature	Hammel	17 Nov 2023 14:42	30	3.0 - Corrino
775	04 - Low	In Progress	Check if migration to Buildroot recommended customizations is warranted	Action Item	Hammel	16 Oct 2023 20:00	30	3.0 - Corrino
589	04 - Low	In Progress	Monitor Setup	Feature	Hammel	23 Mar 2020 10:22	30	0.5.0
254	04 - Low	In Progress	Investigate use of Wifi Direct	Feature	Hammel	26 Oct 2023 22:21	0	3.0 - Corrino
988	05 - Very Low	In Progress	Add Battery status to launcher for xeon.	Feature	Hammel	20 Nov 2023 22:59	10	3.0 - Corrino
794	05 - Very Low	In Progress	Add URL streaming option for AutoKiosk system	Feature	Hammel	24 Apr 2023 22:19	10	3.0 - Corrino
676	05 - Very Low	In Progress	Verify breadboard designs in Fritzing are up to date	Documentation	Hammel	23 Mar 2020 09:59	20	0.5.0
472	05 - Very Low	In Progress	Boot time speedups	Action Item	Hammel	20 May 2023 21:37	70	3.0 - Corrino
122	Critical	In Progress	Create opkg for toolchain debug tools	Action Item	Hammel	23 Sep 2012 20:46	50	0.08.0 - DSP/SGX
95	Medium	In Progress	Verify DSP/gstreamer tools allow video playback	Testing	Hammel	28 Oct 2012 17:00	70	0.08.0 - DSP/SGX

Urgent (62)

1096	01 - Critical	New	Need a log rotator	Feature	Hammel	12 Jan 2024 10:49	0	3.0 - Corrino
971	01 - Critical	New	PiCam starts to lag, then crashes.	Bug	Hammel	16 May 2023 16:39	0	3.0 - Corrino
965	01 - Critical	New	Review alternatives to RaspberryPi due to supply chain issues	Action Item	Hammel	15 Jun 2023 12:05	0	3.0 - Corrino
941	01 - Critical	New	Long pause after restart and animation stops	Bug	Hammel	26 Feb 2023 11:13	0	3.0 - Corrino
936	01 - Critical	New	Switching webcam resolutions is flakey.	Bug	Hammel	21 Feb 2023 16:00	0	3.0 - Corrino
935	01 - Critical	New	dhcpcd.conf does not contain the correct interface IP network.	Bug	Hammel	21 Feb 2023 15:36	0	3.0 - Corrino
926	01 - Critical	New	Scanner not working if dongle connected after boot.	Bug	Hammel	01 Dec 2022 13:48	0	3.0 - Corrino
920	01 - Critical	New	Typing any key other than forward/back arrows locks up the app	Bug	Hammel	16 Nov 2023 14:54	0	3.0 - Corrino
919	01 - Critical	New	Can't get web interface on media system	Bug	Hammel	23 Nov 2022 15:30	0	3.0 - Corrino
887	01 - Critical	New	Update all cross.sh for new HW/BIT of dev platform	Feature	Hammel	20 May 2023 22:17	0	3.0 - Corrino
878	01 - Critical	New	Add ustreamer to support rtsp/h.264 to mjpeg streaming	Feature	Hammel	24 Jan 2022 13:21	0	3.0 - Corrino
804	01 - Critical	New	networkRestart should fork/exec instead of system(cmd)	Bug	Hammel	20 May 2023 19:44	0	3.0 - Corrino
802	01 - Critical	New	Add support for GM_COMMIT	Feature	Hammel	20 May 2023 19:45	0	3.0 - Corrino
744	01 - Critical	New	add webcam motion detection	Feature	Hammel	20 May 2023 19:46	0	3.0 - Corrino
730	01 - Critical	New	Add upgrade tools	Feature	Hammel	20 May 2023 19:46	0	3.0 - Corrino
636	01 - Critical	New	If wlan0 does not support more than one channel then client and AP must use same channel	Bug	Hammel	23 Mar 2020 10:32	0	0.9.0
175	01 - Critical	New	Addon: network configuration	Feature	Hammel	09 Mar 2013 16:01	0	Beta 1
1139	02 - High	New	Make sure KMS is being used and fbftt is deprecated	Feature	Hammel	27 Apr 2024 11:10	0	3.0 - Corrino
1078	02 - High	New	Moisture Sensor	Feature	Hammel	16 Nov 2023 10:08	0	3.0 - Corrino
993	02 - High	New	PiSentry: sometimes takes awhile to exit. And may not restart without power cycle.	Bug	Hammel	23 May 2023 15:00	0	3.0 - Corrino

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
970	02 - High	New	Enable ccache use in all builds.	Action Item	Hammel	16 May 2023 15:10	0	3.0 - Corrino
944	02 - High	New	On RPi 1, change animation to 90 degree rotations	Feature	Hammel	02 Jun 2023 15:26	0	3.0 - Corrino
937	02 - High	New	Crash after channel selection	Bug	Hammel	21 Feb 2023 19:48	0	3.0 - Corrino
925	02 - High	New	IP address does not get updated when switching between interfaces	Bug	Hammel	01 Dec 2022 13:43	0	3.0 - Corrino
923	02 - High	New	Setting new time does not stick	Bug	Hammel	29 Nov 2022 16:18	0	3.0 - Corrino
922	02 - High	New	When in artist mode and browsing, ESC could take you back to artist mode.	Bug	Hammel	29 Nov 2022 16:02	0	3.0 - Corrino
921	02 - High	New	Playback doesn't support FF and Rewind features of omxplayer	Bug	Hammel	29 Nov 2022 16:01	0	3.0 - Corrino
899	02 - High	New	Add docker builds for rpm and deb distros	Feature	Hammel	02 Jun 2023 15:23	0	3.0 - Corrino
892	02 - High	New	Details->Real Title is not cleared with new entry display	Bug	Hammel	27 Feb 2022 16:08	0	3.0 - Corrino
890	02 - High	New	Multipart titles don't get found	Bug	Hammel	27 Feb 2022 16:04	0	3.0 - Corrino
798	02 - High	New	Sensor: 4 port power switch	Action Item	Hammel	16 Nov 2023 14:24	0	3.0 - Corrino
759	02 - High	New	Add packaging to metabuild	Feature	Hammel	20 May 2023 19:48	0	3.0 - Corrino
675	02 - High	New	Code cleanup in imrest	Bug	Hammel	23 Mar 2020 10:34	0	0.9.0
611	02 - High	New	tslib very out of date	Action Item	Hammel	19 May 2023 11:55	0	3.0 - Corrino
159	02 - High	New	keyboard/mouse input doesn't work when xbmc starts	Bug	Hammel	10 Feb 2013 14:51	0	Beta 1
135	02 - High	New	Need to integrate add-ons build to xbmcbox	Feature	Hammel	10 Feb 2013 14:43	0	Beta 1
1133	03 - Medium	New	pinet configure scripts enable-xeon doesn't work on Debian 12.	Bug	Hammel	23 Apr 2024 20:37	0	3.0 - Corrino
1053	03 - Medium	New	Add support for retrieving and selecting alternative posters	Feature	Hammel	20 Oct 2023 14:32	0	3.0 - Corrino
1052	03 - Medium	New	Add support for scanning an individual selection	Feature	Hammel	20 Oct 2023 14:29	0	3.0 - Corrino
1051	03 - Medium	New	Add support for multi-part videos	Bug	Hammel	20 Oct 2023 14:24	0	3.0 - Corrino
1011	03 - Medium	New	Remove or disable keyboard handling bits from pmsui	Feature	Hammel	30 Jul 2023 10:06	0	3.0 - Corrino
990	03 - Medium	New	Streaming RTSP cameras as webcams	Alternative Idea	Hammel	04 Jul 2023 21:20	0	3.0 - Corrino
933	03 - Medium	New	Disabling an interface and saving/applying does not update the IP field	Bug	Hammel	21 Feb 2023 14:00	0	3.0 - Corrino
930	03 - Medium	New	Show only notes in a given category	Feature	Hammel	13 Jan 2023 14:32	0	Writers Workshop
828	03 - Medium	New	All daemons need shutdown in prerm	Bug	Hammel	20 May 2023 19:51	0	3.0 - Corrino
608	03 - Medium	New	Add daemon mode to imgpio	Feature	Hammel	23 Mar 2020 10:32	0	0.9.0
302	03 - Medium	New	JSONParser reports errors to console	Bug	Hammel	23 Mar 2020 10:32	0	0.9.0
643	05 - Very Low	New	Build backup imlightsw circuits	Action Item	Hammel	23 Mar 2020 10:32	0	0.9.0
125	Critical	New	Integrate new xorg driver	Action Item	Hammel	28 Oct 2012 17:02	0	0.08.0 - DSP/SGX
1000	01 - Critical	In Progress	Validate VideoFE against a large database.	Testing	Hammel	23 Oct 2023 20:44	10	3.0 - Corrino
745	01 - Critical	In Progress	Add webcam recordings	Feature	Hammel	11 Oct 2023 22:22	10	3.0 - Corrino

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
715	01 - Critical	In Progress	Why is image (re: picture) display so slow?	Bug	Hammel	20 May 2023 20:27	60	3.0 - Corrino
1073	02 - High	In Progress	Make rk818-bat stop spewing to serial console	Bug	Hammel	14 Jan 2024 16:58	70	3.0 - Corrino
958	02 - High	In Progress	Update pmwiki documentation	Documentation	Hammel	15 Jun 2023 19:40	50	3.0 - Corrino
731	02 - High	In Progress	Automate upgrades	Feature	Hammel	20 May 2023 19:48	10	3.0 - Corrino
1054	03 - Medium	In Progress	Grab genre list next to video json	Feature	Hammel	24 Oct 2023 15:28	10	3.0 - Corrino
972	03 - Medium	In Progress	Plans for 3.0 - Corrino release.	Design	Hammel	25 Aug 2023 09:52	10	3.0 - Corrino
586	03 - Medium	In Progress	PiSensor App config/browse	Feature	Hammel	23 Mar 2020 10:19	20	0.9.0
440	04 - Low	In Progress	wifi/hostapd generates lots of log messages	Bug	Hammel	20 May 2023 20:49	20	3.0 - Corrino
830	05 - Very Low	In Progress	pinet crashes at button press	Bug	Hammel	20 May 2023 20:50	10	3.0 - Corrino
289	05 - Very Low	In Progress	Port RTL8188CUS driver to PiBox	Action Item	Hammel	20 May 2023 20:47	70	3.0 - Corrino
116	High	In Progress	Add Meego UI for connman as a Buildroot package	Feature	Hammel	14 Jul 2012 22:13	0	0.08.0 - DSP/SGX
High (28)								
932	01 - Critical	New	Allow passing command line arguments via shell script.	Feature	Hammel	21 Feb 2023 11:00	0	Writers Workshop
891	01 - Critical	New	Bad titles should be editable and re-scanned.	Bug	Hammel	27 Feb 2022 16:06	0	3.0 - Corrino
504	01 - Critical	New	IoT security	Feature	Hammel	23 Mar 2020 10:29	50	1.0.0 - Hari Seldon
781	02 - High	New	Add UI for system configuration	Feature	Hammel	20 May 2023 19:56	0	3.0 - Corrino
776	02 - High	New	Add theme selection capability with preview	Action Item	Hammel	20 May 2023 20:03	0	3.0 - Corrino
555	02 - High	New	Lockup when USB stick runs out of space	Bug	Hammel	20 May 2023 21:26	0	3.0 - Corrino
487	02 - High	New	Do something with msgQueue/Processor functions in libpibox	Action Item	Hammel	20 May 2023 19:55	0	3.0 - Corrino
992	03 - Medium	New	PiNet sets wireless power off.	Bug	Hammel	23 May 2023 13:59	0	3.0 - Corrino
966	03 - Medium	New	Consider migrating to full AV bridging for webcam support	Feature	Hammel	03 May 2023 09:26	0	3.0 - Corrino
953	03 - Medium	New	Migrate to SPDX license header in all source code, including apps	Action Item	Hammel	30 Mar 2023 14:19	0	3.0 - Corrino
903	03 - Medium	New	New "Large Term" should be same as initial large term	Bug	Hammel	24 Sep 2022 14:39	0	3.0 - Corrino
902	03 - Medium	New	Default of TKIP with WPA2 should be changed to CCMP	Bug	Hammel	20 Sep 2022 17:26	0	3.0 - Corrino
901	03 - Medium	New	GUI writes empty nameserver entries	Bug	Hammel	20 Sep 2022 16:29	0	3.0 - Corrino
900	03 - Medium	New	Non-keypad arrows keys crash the GUI	Bug	Hammel	20 Sep 2022 16:25	0	3.0 - Corrino
868	03 - Medium	New	webui webcam has white bar across the bottom.	Bug	Hammel	01 Nov 2021 22:05	0	3.0 - Corrino
862	03 - Medium	New	piboxMsg() wants response length followed by response but not all messages provide it	Bug	Hammel	20 May 2023 20:04	0	3.0 - Corrino
750	03 - Medium	New	Extend pmsg tests	Testing	Hammel	20 May 2023 20:04	0	3.0 - Corrino
631	03 - Medium	New	Init scripts should use \$() syntax instead of back-ticks for grabbing output from a command.	Action Item	Hammel	20 May 2023 21:25	0	3.0 - Corrino
593	03 - Medium	New	door/window sensor	Feature	Hammel	23 Mar 2020 10:26	0	1.0.0 - Hari Seldon

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
578	03 - Medium	New	Monitor Enclosure	Feature	Hammel	23 Mar 2020 10:17	0	1.0.0 - Hari Seldon
110	Critical	New	verify build on Ubuntu	Action Item	Hammel	11 May 2012 09:10	0	0.07.0 - Networking
68		In Progress	Need to change binary prefixes from mb to bui to differentiate from matchbox code	Testing	Hammel	26 Mar 2012 22:02	0	
441	02 - High	In Progress	Add display rotatation/flip	Action Item	Hammel	20 May 2023 21:41	0	3.0 - Corrino
1049	03 - Medium	In Progress	Write network events to FIFO file.	Feature	Hammel	01 Nov 2023 22:21	10	3.0 - Corrino
160	03 - Medium	In Progress	The Raspbmc addon is broken when applied to PiBox	Bug	Hammel	09 Mar 2013 17:57	10	Beta 2
994	05 - Very Low	In Progress	In PiSentry, there are two icons but aligned for three	Bug	Hammel	26 Oct 2023 15:01	10	3.0 - Corrino
101	Critical	In Progress	add omapfbplay to rootfs build	Feature	Hammel	21 Apr 2012 20:52	20	0.08.0 - DSP/SGX
9	Medium	Feedback	Surf package for buildroot	Feature	Hammel	12 Mar 2011 22:06	60	0.10.0 - BUI Features
Normal (69)								
96		New	enable audio support	Testing	Hammel	21 Apr 2012 20:54	0	0.11.0 - Preview Release
11		New	Track availability of Flash on ARM	Testing	Hammel	28 Feb 2011 10:19	20	1.0 - Galileo
10		New	Review open source flash players	Testing	Hammel	28 Feb 2011 10:19	10	1.0 - Galileo
806	02 - High	New	Update wiki message API documentation	Documentation	Hammel	23 Jun 2023 13:17	0	3.0 - Corrino
633	02 - High	New	Crashes on Ironman distro	Bug	Hammel	20 May 2023 20:28	0	2.0 - Harkonnen
995	03 - Medium	New	Add option to clone using https instead of git	Feature	Hammel	24 May 2023 15:30	0	3.0 - Corrino
983	03 - Medium	New	Investigate towboot installed to eMMC	Action Item	Hammel	18 May 2023 16:31	0	Xeon 1.0 - Asimov
982	03 - Medium	New	Rebuild tow-boot to default to PiBox Dev Platform	Feature	Hammel	18 May 2023 16:30	0	Xeon 1.0 - Asimov
854	03 - Medium	New	Consider ReadTheDocs for documentation	Documentation	Hammel	04 Oct 2021 15:16	0	3.0 - Corrino
774	03 - Medium	New	Verify Buildroot uses BR2_PER_PACKAGE_DIRECTORIES	Bug	Hammel	26 Jul 2023 16:55	0	3.0 - Corrino
756	03 - Medium	New	PiRadio	Feature	Hammel	11 Apr 2020 11:03	0	3.0 - Corrino
752	03 - Medium	New	Videolib sometimes doesn't exit with File->Quit	Bug	Hammel	20 May 2023 20:43	0	3.0 - Corrino
711	03 - Medium	New	Reduce power consumption when not in use	Action Item	Hammel	18 May 2023 12:05	0	Xeon 1.0 - Asimov
702	03 - Medium	New	Need Contacts App	Feature	Hammel	18 May 2023 12:07	0	Xeon 1.0 - Asimov
565	03 - Medium	New	Multiple IP Address fields	Bug	Hammel	20 May 2023 20:43	0	3.0 - Corrino
516	03 - Medium	New	Finish port of msgQueue/queueProessor	Action Item	Hammel	20 May 2023 21:33	0	3.0 - Corrino
483	03 - Medium	New	Need pncShutdown to reverse pncInit and clear all lists	Bug	Hammel	20 May 2023 21:35	0	3.0 - Corrino
482	03 - Medium	New	Add remote connection option	Action Item	Hammel	29 Dec 2015 18:12	0	4.1
481	03 - Medium	New	Consider adding support for Markup language	Action Item	Hammel	29 Dec 2015 18:10	0	4.1
480	03 - Medium	New	Add ability to link various notes together	Action Item	Hammel	13 Jan 2023 14:33	0	4.1
479	03 - Medium	New	Add porter-stemmer to search functions	Action Item	Hammel	29 Dec 2015 18:10	0	4.1

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
478	03 - Medium	New	encrypt notes	Testing	Hammel	29 Dec 2015 17:42	0	4.1
477	03 - Medium	New	Flesh out build.help for current version.	Bug	Hammel	29 Dec 2015 17:40	0	4.1
476	03 - Medium	New	Add configurable autosave period to boot.propertie	Bug	Hammel	29 Dec 2015 17:39	0	4.1
475	03 - Medium	New	Upgrade SWT	Bug	Hammel	29 Dec 2015 17:43	0	4.1
474	03 - Medium	New	Integrate CDSshelf	Bug	Hammel	29 Dec 2015 17:34	0	4.1
368	03 - Medium	New	Add support for WiiMote	Bug	Hammel	20 May 2023 21:58	0	3.0 - Corrino
367	03 - Medium	New	May need a way to stabilize webcam	Feature	Hammel	20 May 2023 22:01	0	3.0 - Corrino
365	03 - Medium	New	Customizations should go on vfat partition, not under /etc	Bug	Hammel	20 May 2023 22:04	0	3.0 - Corrino
319	03 - Medium	New	-t option is not working on the desktop	Bug	Hammel	20 May 2023 22:06	0	3.0 - Corrino
212	03 - Medium	New	Review integration of SPI and I2C support	Feature	Hammel	18 Oct 2013 09:11	0	3.0 - Corrino
149	04 - Low	New	Create Beta 1 release	Packaging	Hammel	10 Feb 2013 14:44	0	Beta 1
150	05 - Very Low	New	Announce Beta1 to News	Action Item	Hammel	10 Feb 2013 14:44	0	Beta 1
86	Low	New	Create an XBMC build - make it an opkg	Feature	Hammel	28 Feb 2011 10:22	0	1.0 - Galileo
60	Low	New	Fix the S-Video output overscan problem.	Bug	Hammel	02 Mar 2011 20:34	0	1.0 - Galileo
83	Medium	New	Panel crashes when I click on it on BeagleBoard	Bug	Hammel	26 Mar 2012 22:02	50	1.0
42	Medium	New	Update env vars in u-boot code	Feature	Hammel	02 Mar 2011 20:40	10	1.0 - Galileo
41	Medium	New	Configuration information should be cached before writing to SD card	Feature	Hammel	26 Mar 2012 22:02	0	1.0
16	Medium	New	Add a boot splash and turn off console output	Feature	Hammel	28 Feb 2011 10:17	10	1.0 - Galileo
14	Medium	New	Tool for creating URL snapshots	Feature	Hammel	26 Mar 2012 22:02	0	1.0
5	Medium	New	UI Configuration Tool	Feature	Hammel	26 Mar 2012 22:02	0	1.0
62		In Progress	Write up on the wiki how to modify the boot script, build it and use it	Testing	Hammel	12 Mar 2011 22:05	0	1.0 - Galileo
32		In Progress	Support Xrm for simplified configuration capabilities.	Testing	Hammel	26 Mar 2012 22:02	0	1.0
1033	02 - High	In Progress	Preload icons	Feature	Hammel	16 Nov 2023 14:45	20	3.0 - Corrino
1116	03 - Medium	In Progress	Add support for styles to pigtk	Feature	Hammel	09 Apr 2024 21:35	10	3.0 - Corrino
1032	03 - Medium	In Progress	Speed up animation	Feature	Hammel	11 Sep 2023 19:43	10	3.0 - Corrino
984	03 - Medium	In Progress	Make a list of required apps for 3.0 release	Design	Hammel	16 Nov 2023 14:21	90	3.0 - Corrino
792	03 - Medium	In Progress	Try adding opengl to cairo in Launcher	Feature	Hammel	12 Sep 2023 09:19	70	3.0 - Corrino
732	03 - Medium	In Progress	PiBox with Docker	Feature	Hammel	23 Oct 2020 16:30	40	3.0 - Corrino
728	03 - Medium	In Progress	Review possible DRM with X.org	Action Item	Hammel	20 May 2023 20:40	20	3.0 - Corrino
708	03 - Medium	In Progress	Need network config app	Feature	Hammel	18 May 2023 12:06	20	Xeon 1.0 - Asimov
526	03 - Medium	In Progress	Consider migrating to using Plex database	Action Item	Hammel	25 Feb 2019 15:19	10	3.0 - Corrino
490	03 - Medium	In Progress	ESP8266 sleep while maintaining wifi	Feature	Hammel	23 Mar 2020 10:05	10	1.0.0 - Hari Seldon

#	Severity	Status	Subject	Tracker	Assignee	Updated	% Done	Target version
460	03 - Medium	In Progress	Review BananaPi as replacement for RaspberryPi	Testing	Hammel	20 May 2023 20:41	30	3.0 - Corrino
384	03 - Medium	In Progress	Add support for interfacing with display via Android	Feature	Hammel	20 May 2023 21:57	50	3.0 - Corrino
848	04 - Low	In Progress	lcdshow pkg install - can't read etc/modules	Bug	Hammel	20 May 2023 20:44	60	3.0 - Corrino
371	04 - Low	In Progress	Media Server and Media Player case models	Action Item	Hammel	25 Feb 2019 15:32	30	3.0 - Corrino
24	Critical	In Progress	Remove XML and themes from window manager	Feature	Hammel	26 Mar 2012 22:02	70	
63	High	In Progress	Make a patch against u-boot BeagleBoard config to reduce boot delay to build-configurable time.	Feature	Hammel	12 Mar 2011 22:01	0	0.08.0 - DSP/SGX
35	High	In Progress	Make panels that slide in from the sides.	Feature	Hammel	26 Mar 2012 22:02	0	1.0
7	High	In Progress	Need a scrolling menu applet for the panel	Feature	Hammel	26 Mar 2012 22:02	20	1.0
53	Low	In Progress	dd of rootfs image doesn't use up full 2nd partition on SD card	Bug	Hammel	15 Nov 2010 19:32	0	1.0 - Galileo
34	Low	In Progress	Does the window manager need XComposite support?	Bug	Hammel	26 Mar 2012 22:02	0	1.0
33	Low	In Progress	X cursor should auto-hide after (N) periods of inactivity.	Feature	Hammel	26 Mar 2012 22:02	0	1.0
31	Low	In Progress	Allow no more than (N) non-panel clients.	Feature	Hammel	26 Mar 2012 22:02	0	1.0
30	Low	In Progress	Make panel clients raise above all other clients.	Feature	Hammel	26 Mar 2012 22:02	0	1.0
29	Low	In Progress	Make panel clients raise above all other clients.	Feature	Hammel	26 Mar 2012 22:02	0	1.0
28	Low	In Progress	Make all X clients except panels full screen.	Feature	Hammel	26 Mar 2012 22:02	0	1.0
64	Medium	In Progress	Boot time improvements	Bug	Hammel	08 Dec 2010 21:15	0	1.0 - Galileo
Low (14)								
600	03 - Medium	New	Admin configuration: web	Feature	Hammel	23 Mar 2020 10:12	0	2.0.0 - Dors Venabili
599	03 - Medium	New	View sensor status: web	Feature	Hammel	23 Mar 2020 10:11	0	2.0.0 - Dors Venabili
598	03 - Medium	New	Admin configuration: mobile	Feature	Hammel	23 Mar 2020 10:10	0	2.0.0 - Dors Venabili
597	03 - Medium	New	View sensor status: mobile	Feature	Hammel	23 Mar 2020 10:10	0	2.0.0 - Dors Venabili
592	03 - Medium	New	Sensor Enclosure	Feature	Hammel	23 Mar 2020 10:26	0	2.0.0 - Dors Venabili
591	03 - Medium	New	battery power	Feature	Hammel	23 Mar 2020 10:23	0	2.0.0 - Dors Venabili
587	03 - Medium	New	Contacts UI	Feature	Hammel	23 Mar 2020 10:20	0	2.0.0 - Dors Venabili
584	03 - Medium	New	Battery backup	Feature	Hammel	23 Mar 2020 10:17	0	2.0.0 - Dors Venabili
575	03 - Medium	New	Backup Battery Circuit board	Feature	Hammel	23 Mar 2020 10:13	0	2.0.0 - Dors Venabili
574	03 - Medium	New	2G/3G support based on Raspberry Pi phone build	Feature	Hammel	23 Mar 2020 10:12	0	2.0.0 - Dors Venabili
210	04 - Low	New	Research fail2ban	Feature	Hammel	18 Oct 2013 09:17	0	3.0 - Corrino
500	05 - Very Low	New	Implement stepper motor control	Feature	Hammel	23 Mar 2020 09:55	0	2.0.0 - Dors Venabili
173	05 - Very Low	New	Timestamp variable TM is not updated on the fly	Bug	Hammel	20 May 2023 22:11	0	3.0 - Corrino
324	03 - Medium	In Progress	usbhandler.sh needs to support multiple modules per device	Bug	Hammel	13 May 2014 23:09	10	3.0 - Corrino